

RECOMMENDED SEATING ARRANGEMENTS



WALKER BAY

⚠ WARNING

According to the American Boat and Yacht Council's standard H-28.5.1 recommended seating arrangement must be specified.

RISK OF FALLING OVERBOARD

Recommended seating positions are marked with this symbol: 

Add additional persons in the sequences of numbers shown.

Do not exceed maximum persons or weight capacity.


See Capacity Label located on boat's helm for maximum capacities.

Avoid sharp turns at high speeds. Sharp turns at high speeds may result in passengers falling overboard.


Distribute weight of persons and gear evenly throughout boat.

When sitting on inflatable tubes use hand holds provided on tubes.


Generation LTE Console RIBs




Generation 10 LTE
(3 Seats)




Generation 10 LTE
(4 Seats)




Generation 11 LTE
(3 Seats)




Generation 11 LTE
(4 Seats)




Generation 12 LTE
(4 Seats)




Generation 12 LTE
(5 Seats)




Generation 13LTE
(4 Seats)



Generation 13LTE
(5 Seats)




Generation 14LTE
(4 Seats)




Generation 14LTE
(5 Seats)


Venture Console RIBs




Venture 13
(4 seats)




Venture 13
(5 seats)




Venture 14
(4 seats)



Venture 14
(5 seats)



Venture 16
(4 seats)




Venture 16
(5 seats)

RECOMMENDED SEATING ARRANGEMENTS




WALKER BAY


Generation Console RIBs




Generation 340 Dlx &
Generation 360 Dlx




Generation 400 Dlx




Generation 450 Dlx



Generation 525 Dlx




Generation 12 Dlx




Generation 15 Dlx

Odyssey ST Console RIBs



Odyssey 325ST
Console



Odyssey 365ST
Console